

歐品電子(昆山)有限公司

OUPIN ELECTRONIC(KUNSHAN) CO.,LTD.

PACKAGING SPECIFICATION (包 裝 作 業 規 范)

CONFIDENTIAL

TOP SECRET

PAGE	1/4	REV.	X1
PACKAGING CATEGORY (包裝方式)		PE BAG PACKING	

SPEC.NO.(規範編號)	Q9120SPP-1461		
APPLICABLE CUSTOMER (適用客戶)	ALL	APPLICABLE PRODUCT (適用產品)	9120-2P02ASX120-A001

REVISION HISTORY (修 訂 履 歷)

ECN REV. NO	PAGE (頁 次)								
	1	2	3	4					
A	New 新版								

DIVISION (事業單位)	Product Development (產品開發課)	APPROVED (核 准)	CHECKED (審 核)	PREPARED (制 表)	WCC 09/22"25
--------------------	----------------------------------	-------------------	------------------	-------------------	--------------

歐品電子(昆山)有限公司

OUPHIN ELECTRONIC(KUNSHAN) CO.,LTD.

PACKAGING SPECIFICATION (包裝作業規範)


☒ CONFIDENTIAL ☐ TOP SECRET

PAGE 2/4 REV. X1

SPEC.NO.(規範編號) Q9120SPP-1461

PACKING OPERATION DIAGRAM & INSTRUCTION (包裝作業圖示及說明)

REMARK (備 注)



Paper Box : CT-0
(紙箱 : CT-0)



PE 15*40(T=0.5)

一.Packing Mode: (包裝方式)

(1).PE bag 30*40 (T=0.5) , CT-0 paper bag, drying agent.
(PE袋 30*40 (T=0.5) , CT-0紙盒 , 干燥劑)

(2).Take 1PCS PE bag (30*40) cut into two pieces(15*40) and put 1PCS in each bag, then put one bag of drying agent, seal the opening of bag, stick certificate of quality designation list on the outside. Write P/N, Product batch number, quality and store list number (as shown in drawing).

(取1PCS PE袋 (30*40)裁成兩塊(15*40),每個袋子放1PCS,然後將袋子中各放一袋干燥劑,再把袋口處捏緊,外面貼合格證標示單,,分別寫料號,生產批號,數量及入庫單號(如圖所示).

歐品電子(昆山)有限公司

OUPIIN ELECTRONIC(KUNSHAN) CO.,LTD.

PACKAGING SPECIFICATION (包裝作業規範)

☒ CONFIDENTIAL ☐ TOP SECRET

SPEC.NO.(規範編號) Q9120SPP-1461

PAGE


3/4

REV.

X1


PACKING OPERATION DIAGRAM & INSTRUCTION (包裝作業圖示及說明)

REMARK (備 注)



CT-0 paper box , lay two cases at each layer , three layers in all.
(CT-0紙盒, 每層放2盒, 共擺放三層)

Drawing One
(圖一)



Drawing Two
(圖二)

一.Outer box packing mode: (外箱包裝方式)

- (1). Paper box CT- 1.6 Standard 1 PCS,as shown in drawing One.
(紙箱CT-1.6規格 1 PCS.如(圖一)所示)
- (2).Put one Air Column Bag in the upper and lower of the paper box,2PCS in all,as shown in drawing One.
(每箱上下各放一塊氣柱袋,共2PCS , 如(圖一)所示)
- (3). Put waterproof bag 1 PCS in the paper box.
(紙箱內側放入防水袋 1 PCS.)
- (4). Put CT-0 paper box filled with finished product in the waterproof bag, lay them in three layers,two paper boxes in one layer,six cases in all.
(于防水袋內放入裝滿成品的CT-0盒子, 分三層放入, 每層放2個CT-0盒子, 即共放入6盒.)
- (5).Seal the waterproof bag,then put the Air ColumnBoard 1PCS on the bag.
(Put 1 PCS Air Column Board at the right and left side in the paper box if it is necessary.)
(封上防水袋,然後放上第二塊氣柱袋,未填滿處用氣柱袋填滿.)
(必要時,在紙箱的左右兩側各放一塊氣柱袋)
- (6).Seal the surface of the outer box,as shown in drawing Two.
(將外箱上層封口.如(圖二)所示)

The form on the right and flank side of the box must be filled correctly and clearly, take actual testing weight as the standard of every box gross weight.
(外箱之正麥和側麥所要填寫之項目要填寫正確,清晰,每箱之毛重應以實測重量為準)

歐品電子(昆山)有限公司

OUPUIN ELECTRONIC(KUNSHAN) CO.,LTD.

PACKAGING SPECIFICATION (包裝作業規範)

							☒ CONFIDENTIAL ☐ TOP SECRET				
SPEC.NO.(規範編號)		Q9120SPP-1461					PAGE:	4/4	REV.	X1	
PACKING MATERIAL (包裝材料)			PRODUCT P/N		PACKING N.W.		PACKING QUANTITY (包裝數量)			WEIGHT (重量) kg	
MATERIAL NAME (材料名稱)		PART NO. (料號)	Q'TY	(產品料號)		(包材重量)		PCS/CT-0	CT-0/BOX	PCS/BOX	N.W./PCS N.W./BOX G.W./BOX
PAPER BOXES (紙箱)		CT-1.6	1	9120-2P02ASX120-A001		2.27		4	6	24	0.5 12.00 14.77
INNER PAPER BOXES (內紙箱)		CT-0	6								
WATERPROOF BAG (防水袋)		PE 100*90	1								
PE PACKING BAG (PE包裝袋)		30*40	12								
DRYING AGENT (干燥劑)		-----	24								
1.NOTE: (注意) When the finished products have been made,take the actual weight as the standard of gross weight in each box. (成品出貨時,每箱之毛重應以實測重量為準) When the finished products have been made,stick the proper designation list on the box according to product demand. (成品出貨時,依據出貨要求貼上相對應的標籤單)											