

歐品電子(昆山)有限公司

OUPIN ELECTRONIC(KUNSHAN) CO.,LTD.

PACKAGING SPECIFICATION (包 裝 作 業 規 范)

☒ CONFIDENTIAL

☐ TOP SECRET

PAGE	1/4	REV.	A
PACKAGING CATEGORY (包裝方式)		PE BAG PACKING	

SPEC.NO.(規範編號)	Q9120SPP-1441		
APPLICABLE CUSTOMER (適用客戶)	ALL	APPLICABLE PRODUCT (適用產品)	9120-2P02AWX325-A001

REVISION HISTORY (修 訂 履 歷)

ECN REV. NO	PAGE (頁 次)								
	1	2	3	4					
A	New 新版								

DIVISION (事業單位)	Product Development (產品開發課)	APPROVED (核 准)	CHECKED (審 核)	PREPARED (制 表)	Jerry 06/19"25
--------------------	----------------------------------	-------------------	------------------	-------------------	----------------

歐品電子(昆山)有限公司

OUPIN ELECTRONIC(KUNSHAN) CO.,LTD.

PACKAGING SPECIFICATION (包裝作業規範)



☒ CONFIDENTIAL ☐ TOP SECRET

PAGE 2/4 REV. A


SPEC.NO.(規範編號) Q9120SPP-1441

PACKING OPERATION DIAGRAM & INSTRUCTION (包裝作業圖示及說明)

REMARK (備 注)



PE 550*150(T=0.2)



Paper Box : CT-0.9
(紙箱 : CT-0.9)

一.Packing Mode: (包裝方式)

(1).PE bag 550*150(T=0.2) , drying agent.
(PE袋550*150(T=0.2) , 干燥劑)

(2).Take 1PCS PE bag (550*150) , put 1 PCS in each bag, then put one bag of drying agent, seal the opening of bag, stick certificate of quality designation list on the outside.Write P/N, Product batch number, quality and store list number (as shown in drawing).

(取1PCS PE袋 (550*150) ,每個袋子放 1 PCS,然後將袋子中各放一袋干燥劑,再把袋口處捏緊,外面貼合格證標示單,,分別寫料號,生產批號,數量及入庫單號(如圖所示).

歐品電子(昆山)有限公司

OUPIN ELECTRONIC(KUNSHAN) CO.,LTD.

PACKAGING SPECIFICATION (包裝作業規範)

☒ CONFIDENTIAL ☐ TOP SECRET

SPEC.NO.(規範編號) Q9120SPP-1441

PAGE


3/4

REV.


A

PACKING OPERATION DIAGRAM & INSTRUCTION (包裝作業圖示及說明)

REMARK (備 注)



Drawing One
(圖一)



Drawing Two
(圖二)

一.Outer box packing mode: (外箱包裝方式)

- (1). Paper box CT- 0.9 Standard 1 PCS,as shown in drawing One.
(紙箱CT-0.9規格 1 PCS.如(圖1)所示)
- (2).Put one Air Column Bag in the upper and lower of the paper box.,2PCS in all.,as shown in drawing One.
(每箱上下各放一塊氣柱袋,,共2PCS , 如(圖一)所示)
- (3). Put waterproof bag 1 PCS in the paper box.
(紙箱內側放入防水袋 1 PCS.)
- (4). Put PE bag filled with finished product in the waterproof bag, lay them in three layers,five PE bags in one layer, five cases in all.
(于防水袋內放入裝滿成品的PE袋, 分三層放入, 每層放5袋PE袋, 即共放入15袋.)
- (5).Seal the waterproof bag,then put the Air Column Bag 1PCS on the bag. if box can not be fullled ,filled with ploy.
(Put 1 PCS Air Column Bag at the right and left side in the paper box if it is necessary.)
(封上防水袋,然後放上第二塊氣柱袋,未填滿處用氣柱袋填滿.)
(必要時, 在紙箱的左右兩側各放一塊氣柱袋)
- (6).Seal the surface of the outer box,as shown in drawing Three.
(將外箱上層封口.如(圖三)所示)

The form on the right and flank side of the box must be filled correctly and clearly, take actual testing weight as the standard of every box gross weight.
(外箱之正麥和側麥所要填寫之項目要填寫正確,清晰,每箱之毛重應以實測重量為準)

PACKAGING SPECIFICATION (包裝作業規範)

☒CONFIDENTIAL ☐TOP SECRET

WEIGHT (重量) kg

G.W./BOX

18.98

1

15

6

(成品出貨時,依據出貨要求貼上相對應的標籤單)